Please complete every section daily and give to at ENV Station 001.

Date: 2/07/17 Time: 10:45 a. ...
Initials: 102

Outfall 009/010	Answers
Substance discharged?	Y / (N)
-if Yes, Color?	
-If Yes, Size / Area?	p. marine and a second a second and a second a second and
Vac truck amount recovered	Con Col water
Estimated oil recovered	the all
Length of sorbent boom replaced	0
Canal Appearance (winds, sheen, etc.)	nw, 10-15 mph.

Time: 10:15 0. ~ Initials: \_\_\_\_\_\_\_\_\_

Answers	
Y / (N)	
e <sub>ker</sub> enne <sup>†</sup>	
The state of the s	
0	
0	
NW 10-15 L-A	


## Power House Basement Sump Pump Pit Inspection Form

Pit covers must remain on at all times

Date: 2/2//7

Time: 1830

Initials:



Sump Pits	Clean	Oil Sheen & Color	Comments
70k Room	X		- Continuents
6 Turbo Blower		Sump Water (	Diverted to Ach Dit
7 Generator		Sump Water Diverted to Ash Pit Sump Water Diverted to Ash Pit	
5 Turbo Blower	^	Sump Water Diverted to Ash Pit	
7 Turbo Blower	X		overted to ASII Pit
2300VAC Room	X		
8 Generator	7	Sump Water Diverted to Ash Pit	

If oil is found in sump pit contact KM to have the pit cleaned out.